

Sent to Chief Surveyor 7.2.96

Received from Chief Surveyor \_\_\_\_\_

VESSEL'S NAME S. S. Cayo Mono Report Lon No. 57356

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey \_\_\_\_\_

DAMAGE.

Damage through Groundingnow repaired as follows:- Vessel placed in dry dock

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....							
Faired or repaired	<u>19 Removed &amp; re-fitted</u>						

Other items:- stern frame renewed: one bilge keel and cement repaired

It is submitted the vessel is worthy to remain classed

100 A 1  
span deckwith record of Survey 2.96 Lon

as recommended.

W.M.  
28.2.96100 A 1  
span deck  
2.96 LonW.M.  
28.2.96

© 2021

W.M.Lloyd's Register  
Foundation

LON729-0371