

Sent to Chief Surveyor

19. 5. 98

Received from Chief Surveyor

VESSEL'S NAME

S. S. *Albata*

Report

No.

For the CHIEF SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

No. *2*

SURVEY PARTLY HELD.

When due

When proposed to be completed

Portion of Survey held, &c.

A report was recently received from a surveyor nominated by Lloyd's agent at M axatlan from which it appeared that all the requirements of the S. S. No. 2 have been complied with, but he states that the keel plates require to be renewed from middle of vessel to stern frame & that the riveting in same is defective.

In reply to enquiries the owners now state that the keel plates have been ordered & will be shipped from Liverpool on the 23rd inst & will be put in position as soon as possible after arrival.

It is submitted that under the circumstances the owners proposal merits approval and in the meantime the vessel's class might remain undisturbed, record of survey and notation of S. S. No. 2 being deferred.



JDM
 19. 5. 98
C. H. P.
 Lloyd's Register
 Foundation

L0N731-0282