


s.s. "ASTER".

In this case it is observed that the diameter of the four lengths of chain cable, which the Owners request to be allowed to place on board this vessel, is 1/16" in excess of that required by the Society's Rules.

The Marseilles Surveyors state that the cable, which has been tested by the Bureau Veritas, has been examined by them and found satisfactory, and compared with the certificates of test issued by that Classification Society.

The tests applied, as given on the certificates forwarded by the Surveyors, are equal to this Society's requirements, and it is submitted that in this case the four lengths of chain cable might be accepted, and the Marseilles Surveyors informed accordingly.

 19.2.29. R/10



© 2021

Lloyd's Register
Foundation

0120-738222

TONNAGE F
Aver
BEAMS, 1