

Copy -

Sundaland No 149

Chopas Register Office Sundaland

Nov 29th 1884

Dear Sir

On examining the Snow Salus I
found the Hold Beams to have rotted
I hereby recommend you as early as
convenient to put on some iron hanging
staves on each side say 8 on each side
also to put on, a long wood pointer
piece on each quarter from the Wing
Transom; downwards. On your doing the
above work. please let me know. That
I may be enabled to report the same
to the Committee in London.

Yours Truly,

John D. Bunker

Wm. H. Bunker

Sundaland



© 2018

Lloyd's Register
Foundation