

Sunderland No. 913

Lloyd's Register Office

Sunderland 14 April 1858

Charles Graham Esq.
Sir

Your favour of the 6th Lg. has been
only received and in reply to the latter yesterday
the 10th Captain being elapsed only 8 years with
which the River is disengaged. The explanation for
Bruton has to offer. he having made the report in
as follows -

"The vessel was fully timbered and in fact floated
before he was called upon by the Agent of the River
to superintend the Building specially; and was told
"that the Agreement was for an light Iron Ship".
but finding the Frame so generally good in quality
and fairly squared throughout he determined
to be guided by the Equality of working materials
to be guided by the Equality of working materials.



© 2018
Lloyd's Register
Foundation

also the Fastenings, that might be applied: whether a right
to give the name the chance and benefit of realizing the
8 year Grade.

The plank in question of 8m. a few inches above
the first foothold head was upon the keel when he
had took the Inspection in Special Survey and bearing
in mind the quality of material used and general
workmanship and fastenings: he did not consider the
being in fact far superior to what the Rules require for
the 8 year class: he did not consider it reasonable or fair
to call upon the Builder to remove this streak of 8m.
particularly so: as his contract was for 8 years and the
following explanation we hope will further satisfy the
Committee upon the point. By Note the Bishop streak
are worked in regular breadth from the floor heads
upwards and the upper streak happens to be as much
in breadth below as it is above the foothold heads

and this particular plank is one of the thick Bridge⁴
planks. So that in fact the vessel is really stronger
than if it had been a 3^m. French Oak plank.

We believe the ship is in order at present
and it will afford you some satisfaction if you will
direct one or any of the London Surveyors to go on
board and clearly examine every part. We trusting
that they will fully concur in the general report
given from this office. and confirm the opinion
expressed in the recommendation for the ship to be
Chased off.

Hoping this explanation will be satisfactory

We remain Sir

Your ob^r Servt

Benton Winton



© 2018

Lloyd's Register
Foundation

1838

Tunbridge

Brentford

2
6

Septane

10/9/3

London

Combie

2 White Bear Inn

Charles Baldwin Esq

Mr



Mr Charles
Baldwin
Esq
2 White Bear
Inn
Combie
London

SLD924/295 2/2



© 2018

Lloyd's Register
Foundation