

3m.7.40.

W1-0023

30 AUG 1941

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME AFON TOWY Rpt. Nwc No. 99685

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

dated 14.10.40.

The class is subject - see endorsement

The 2nd S.S. No. 2 became due 1.41.

The NEWCASTLE Surveyors report the vessel placed on a slipway, bottom coated and some repairs effected.

Framing in Nos. 1 and 2 holds found wasted, also plating and stiffeners of bunker after bulkhead, and damage to stern bulwarks, but the parts are efficient meantime.


The outstanding items, including No. 2 D.B. tank, as above, examined and found efficient.

It is submitted action be deferred.

Insert in S.V.R.L:-

Rps to framing in Nos. 1 & 2 holds, bunker aft bulkhead, stern bulwarks.

(DOCKING DATE 7.41)



© 2021

Lloyd's Register  
Foundation

27.8.41