

by Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Steel 25. "AFON-TOWY"*

Rpt. *Sou.*

No. *10456.*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

1st Entry.

This vessel is now at Sunderland for her Machinery. To complete the Survey, the decks, Donnan Pump, Steering Gear and Windlass require to be tested; the after peak tanks to test in way of stern tube, & foreboard to verify. The Sunderland Surveyors should be advised, & requested to forward a report on form 8. when the Survey is completed.

The Southampton Surveyors should be informed it is included that the breadth of triple riveted butt laps in stake below sheer, is as required, but the Surveyors should be requested to state if this is so.

Ans 6-2-20

replied 7/2/20

M
Ans 6-2-20

© 2021

Lloyd's Register
Foundation

W1-0035