

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report *Dec 7* 1917 When handed in at Local Office *-7 DEC 1917* Port of *LIVERPOOL*
No. in Survey held at *Liverpool* Date, First Survey *4* Last Survey *Dec 3rd 1917*
Reg. Book. *1/5 on the Wood, Iron or Steel* *S. S. AGUILA* (No. of Visits) Master

TONNAGE:— Built at *Dundee* By whom *Caledon L.B. & Co.* When *1917*
GROSS Owners *Yeoward Bros* Port belonging to
UNDER DK. Owners' Address
NET (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
WB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port
CHARACTER, *100A1*
Date of last Survey and of Periodical Surveys. *Class Bon Temples*
Machinery and Boiler Surveys (including date of N.B., if any).
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR *See Dundee letter dated 19th Nov. 1917.*

The W.T doors at shaft and bunker tunnel now tested & found satisfactory.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Cement or Asphalt (State which.)	Hatches	Condition, how ascertained
Outside Plating	Rudder	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Steering gear and its connections	Caulking ditto	Sails
Rivets	Windlass	Treenails ditto	Equipment letter
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	" length size
Reverse Frames		Ditto ditto at other places ditto	" Rule length size
Floors		Stringers, Clamps & Shells ditto	Hawser & Warps
Keelsons		Salting ditto	Standing & Running Rigging
		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptdn15, &c."

Reported for the information of the Committee.

Survey Fee (per Section 28) £ : : Fees applied for, 19
Special Damage or Repair Fee (if any) £ : : Received by me, 19
(per Sec. 28)
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :

LIVERPOOL -7 DEC 1917

Committee's Minute

Character Assigned

W. Gordon Hay

Surveyor to Lloyd's Register of Shipping.



© 2021

Lloyd's Register Foundation

W1-6153