

go tanks Nos.1,5,7 & 10 filled with water to main deck, a number of doublers fitted
3rd,4th and 5th strakes from top,tanks, tested and proven tight, all remaining tanks to

9-DEC-1944

Chief Surveyors.....

Received from Chief Surveyors.....

SHIP NAME "VACUUM" REPORT N.Yk. No. 45665

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey Further Gen.Exam. When due 12.44. "EXAMINED 10-44", 12 MONTHS

Subject to (15 fathoms of chain cable being supplied).

(Docking date) 10.44
"Examined 10.44".



© 2020

Lloyd's Register Foundation

Y.M. -
on Felt.)
Month
&c.
now ascertained
wedges removed
tter a*
of 3B
if now rang
55 fms
board)
length 270
Stat
arps
Running Rigg
r Book cons
d and to hav
s. now c
ained 10,