

Do. above Crown of
Engine Room ... 23.55
8026.56

sternpost
Longitudinal Number 44273
Depth 6.2

Owners Standard Transport

1

Sent to Chief Surveyors 29.6.17

Received from Chief Surveyors

30 JUN 1917

VESSEL'S NAME *SS. Standard Arrow* Report *Phl* No. *2438*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

When due

The report of pt. comm. should be made in this case.

M 29.6.17

*In Mr. White's note.
Mr. Barker*

[Signature]
3. 4. 17



© 2020

Lloyd's Register Foundation

W1002-0260

W1002-0266

W1002-0267

Bridge Deck Stringer Plate, br'dth & thickness