

ENGINES &c —Description of Engines

LONDON

See S. & Report No. 3635.

SAN FRANCISCO,

November 3, 1921.

Seaton & Higgins
417 California Street
San Francisco, California.

F.G. ARCHBOLD,

The Moore Shipbuilding Company, Builders of the Steel Screw Steamer "BIRCHHEAD" of New York, their Yard No. 166, also P.A. Becker, Esq., Lloyd's Agent, San Francisco, survey the said vessel while lying at Moore Shipbuilding Co.'s Yard, Oakland, on October 24, 1921, for the purpose of ascertaining the nature and extent of damage to Starboard cargo pump alleged to have been caused when testing oil pipe lines October 12, 1921.

For further particulars see statement of Builders to their Brokers, a copy of which is hereto attached.

On examination of Vessel

FOUND

Forward water chamber of starboard pump fractured round center for about 10".

RECOMMENDED

Pump water end to be renewed at Owner's convenience.
All removals necessary in order to carry out these repairs to be afterwards replaced and made good.

NOW DONE

As a temporary repair to allow vessel to proceed on her voyage, a patch was fitted, pump tested and found sound.

(Signed) F.G. Archbold.
Surveyor to Lloyd's Register.

2 amount office

Billed Oct. 3, 1921.



© 2021

Lloyd's Register
Foundation

W1006-0086