

Has a
If so, it

Now DONE :-

VESSEL'S NAME **CONDE**

Report

No. **3** NOV 1944

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in $\frac{m}{m}$ of ~~an inch~~.

STRAKE.	AMIDSHIP.				FORWARD.				AFT.				REMARKS.			
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.		Std.	Port.	Std.
BRIDGE																
DECK SHEER STRAKE	17	16	16.5	1.00	0.50											
Strake below	16.5	15	14.5	1.50	2.50											
SHELTER																
DECK SHEER STRAKE	16.75	17	17	+0.25	+0.50	12.5	12	13	0.5	+0.5	12.5	14	13.5	+1.5	+1	
1st Strake below	17.25	17	16.5	0.25	0.75	12.5	13	11.5	+0.5	1	12.5	13	13.5	+0.5	+1	
2nd " "	17.25	15	15.75	0.25	1.50	12.75	13.5	13.5	+0.75	+0.75	12.75	11.5	12	1.25	0.75	
3rd " "	17.25	14.5	15	2.75	2.25	12.75	13	13	+0.25	+0.25	12.75	11	12	1.75	0.75	
4th " "	17.25	13.5	13	3.75	4.25	12.75	12	13	0.75	+0.25	12.75	12	10	0.75	2.75	
5th " "	17.25	15	17	2.25	0.25	12.75	11.5	9	1.25	3.75	12.75	8.5	8.5	4.75	4.75	
6th " "	17.25	16	16.5	1.25	0.75	12.75	12	10	0.75	2.75	12.75	13	14	+0.25	1.75	
7th " "	17	16.75	17	0.25	-	12.75	13.5	13	+0.75	+0.25	13	16	16.5	+3	+2.5	
8th " "																
9th " "																

Drillings at ends to be made in the vicinity of the peak bulkheads.

W1048-0039

Keels

Stringers

Inner Bottom Plating

Have the Tanks been examined in full

Have Ventilators and their Coamings been examined and found efficient?

Timbers of Frame at openings

" " at other places

Stringers, Clamps & Shelves

Other Items

© 2021

Lloyd's Register
Foundation