

COPY.

Lloyd's Register of Shipping.



Port

Hong Kong

[Faint, mirrored text from the reverse side of the page, including '12th August 1941' and 'Lloyd's Register of Shipping']

This is to Certify that I have

Part

Surveyed ~~the Boiler~~ and Machinery, of ~~the~~ Completion Boiler
Survey and Propeller Shafts of the Twin S.S. "DON JOSE" of
Manila, P.I., 10893 Gross Tons, No. 73285 in the Register Book.

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
Recommended that the record of B.S. 7-41., M.S. with date
when survey completed. Tail Shafts seen C.L. 8-41.

be made in the Register Book in the case of this vessel.

P. T. O.


Chas R Rawcliffe

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

© 2020



Lloyd's Register
Foundation

COPY.

Lloyd's Register of Shipping.



TO COMPLETE H.S.

Electric installation to be examined and tested.
Port & Starboard main engine intermediate shafts, and
Pumping arrangements to be examined.

This is to Certify that I have

Surveyed the ~~Boilers and Machinery~~ ^{Boiler} Completion Boiler
Survey and Propeller Shafts of the Twin S.S. "DON JOHN" of
Mankla, S.I., 10893 Gross Tons, No. 75288 in the Register Book.

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
recommended that the record of S.S. 7-41, K.S., with date
when survey completed. Tail shafts seen C.I. 8-41.

be made in the Register Book in the case of this vessel.

P. T. O.

James R. K... ..

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation

11007-0081