

WRECK SECTION

No. (Received at London Office)

No. 56955

REPORT OF SURVEY FOR REPAIRS, &c.

Report made on 18th. Oct. 1950 ... Port of CARDIFF ... Survey held at CARDIFF ... Date, First Survey 9th. Oct. Last Survey 13th. Oct. 1950

Name: 5252 ... Built at Glasgow ... By whom Harland & Wolff Ltd. ... Owners Naviera Aznar Soc. Anon. ... Port belonging to Bilbao

Afloat or in Dry Dock? Afloat ... Name of Dock Queens Dock ... Particulars of Classification ...

Report No. 56665 ... Port CFF ... Society's Freeboard (if assigned) as painted on Ship and now verified ...

Was a damage report made by anyone else? if so, by whom? ... OR EXAMINATION AS PER RULE, FOR Interim Certificate for Postponement of Special Survey due 7-50

Ship visited, holds, decks, tween decks, casings, ventilator and air pipes, coamings, skylights, companionways, steering arrangements and windlass generally examined. ... Welded doublers fitted in 3rd. stringer plate from aft bulkhead and in 3rd. plate from

Table with columns: DAMAGE REPAIRS :- Shell Plates, Frames, R. Frames, Floors and Bracket Floors, Beams, Inner Bottom Plates, Dk. Plates, Other Items :-

Table with columns: SATISFACTORY, Bulkheads, Engine Room Skylights, Copper, or Y.M., etc.

Observations, Opinion as to Class, Recommendation, &c. :- ... ship in my opinion is eligible to remain as classed without fresh record of survey subject

Gen. Examn. £ 10 : 0 : 0 ... Received by me, ... TUES. 14 NOV 1950

Character Assigned ... Deferred for ... Lloyd's Register Foundation

