

Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

SEL'S NAME "EMPRESS OF AUSTRALIA" REPORT Liverpool No 134389.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey \_\_\_\_\_

Damage

When due \_\_\_\_\_

NOTED

Subject as now recommended, but the surveyor should be asked his recommendation regarding repairs to the Starboard I.P. Turbine Blading. X

Amey

18/1/52



© 2020

Lloyd's Register  
Foundation

4700-9801M

damaged - it was recommended that the stbd  
be lifted and in this case the first two rows of stbd and stbd blades