

Received from Chief Ship Surveyor

24 NOV 1952

NAME

LIANDOVERY CASTLE

REPORT

Lon.

No. 125794

standing Conditions of Class:

Subject to permanent repairs to indented forecastle sheerstrake plates etc. (p.s.), also to indented keel and bottom plating being specially examined and dealt with and the chain cable studs being made good, all at the next drydocking.

sement of Class (B) ~~(As before or None)~~

re of Present Survey: ~~(Afloat and in dry dock)~~ Docking.

Repairs to the indented forecastle sheerstrake plating etc. (p.s.) as above.

Recommendation:

SUBMITTED record of docking 9,52 be assigned, subject to indented keel and bottom plating being specially examined and dealt with, and the chain cable studs being made good by next drydocking, but without other conditions.

9,52 Lon.

Subject
Without.



© 2021

Lloyd's Register
Foundation

W1091-0061