

Lloyd's Register of Shipping

UNITED WITH THE BRITISH CORPORATION REGISTER

1ST FLOOR SHELL HOUSE

P. O. BOX 463

HONG KONG

Classn. (H).

5th August, 1952.

RECEIVED

- 9 AUG 1952

And.....

The Secretary,
Lloyd's Register of Shipping,
LONDON.

Dear Sir,

With reference to your letter of 31st ultimo in regard to the S.S. "BANDRA" we forwarded a Report 10 dated 13th May last detailing the survey held and the recommendations made.

The Owners deferred commencement of repairs due to the present uncertain economic situation and it now appears that the ship is being broken up.

Yours faithfully,

James Anderson

For the Surveyors.

JAA:CMC

W1091-0077

Lloyd's Register
Foundation

(S)

CLASSIFICATION

Robley
2/3

H

Copied for
Publications Dept.

Copied for Finance

SSS
4547


for the Committee

VALUATION

the ship is being broken up.
The owners deferred commencement of repairs due to the present uncertain economic situation and it has not been decided whether to repair or scrap.

The owners deferred commencement of repairs due to the present uncertain economic situation and it has not been decided whether to repair or scrap.

The owners deferred commencement of repairs due to the present uncertain economic situation and it has not been decided whether to repair or scrap.



Dear Sir,

LONDON.

2nd AUG 1952

RECEIVED

2nd AUG 1952

HONG KONG
1st FLOOR SHELL HOUSE
110 BOX 483

Lloyd's Register of Shipping
UNITED WITH THE BRITISH CORPORATION REGISTER

© 2021

Lloyd's Register
Foundation

CABLE ADDRESS: MARINE