

1

106 1927

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Stl.Sc. "MAIMUNA".

Report Lon.

No. 91652a

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

This vessel was built in January 1926 and classed 100A1, "For Coasting Services at Sarawak."

Lloyd's Agents at Sarawak now state they have been informed that it is not the intention of the Owner to maintain the classification.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu indicating withdrawal of class at the Owners' request.

Withdraw class

Insert ...

4. 8. 27.



© 2021

Lloyd's Register  
Foundation

W11100-0037