

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl S.M.V MAIMUNA Rpt. Low No. 89629

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1<sup>st</sup> Long

Transverse No.

1300

Depth "d"

Framing: Table No.

Description angle frames as approved2<sup>nd</sup> Longitudinal No.

4550

Proportions Length  
Depth =

13.0

Deck Sheerstrake

as approved

Revised Rule

This vessel appears to have been built in accordance with the Revised Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A.1. (Steel) For Coasting Services at Sarawak  
1 dk (Stl - pt teaks).  
F.P.T. 17t, A.P.T. 10t  
F.K. 5 B.H. asp. Lloyds A. CP.  
P. 25' B. 49' F 31'.



2021  
16.1.26  
Lloyd's Register  
Foundation

W1100-0047

W1100-0048 13