



Lloyd's Register of Shipping.

HEAD OFFICE: 71, FENCHURCH STREET, LONDON, E.C. 3.

LLOYD'S REGISTER,
LONDON, Port of Naples, (76)

REC'D 30 JAN 1923

Via A. Depretis, 31,

19th January, 1923.

ANS'D _____

Communications to
be sent to
SURVEYORS.

Dear Sir,

We forward herewith our first entry Reports
on the steamer " BAGNOLI I " viz:

Hull Rpt.	No. 2218
Mchy "	" 2218 & 7964 Genoa
Donkey Boiler Rpt.	" 2218
Electric Light "	" 2218

It will be noticed on the machinery Report
that part of the Fees Lire 4259.00 has to be credited
to the Genoa Office when paid.

The approved plans of the machinery and boilers
have been retained at your office see your letter
addressed to Genoa E.28-I-1921 and 6-I-1921.

We have forwarded to day under separate cover
the following approved plans.

(TWO
PACKETS)

- 1) Pumping plan E. & B. spaces.
- 2) Pumping Plan Holds.
- 3) Midship Section.
- 4) Profile.
- 5) Pillars & Girders.
- 6) Stem.



© 2020

Lloyd's Register
Foundation

WH19-00450123 (212)

- 2 -

- 7) Rudder.
- 8) Sternframe.
- 9) Double Bottom.
- 10) Upper deck.
- 11) Awning Deck.
- 12) Web frame on I59.
- 13) Details Hatchways & Pillars.
- 14) Web frame on 20.
- 15) Deep tank cover details.
- 16) " " " "
- 17) Bulkheads I43-I65.
- 18) " 80-I05-I22.
- 19) " I2-29-54.
- 20) " 39-42.

We are, Dear Sir,

Yours faithfully,

The Surveyors to Lloyd's Register

The Secretary,

LONDON.



© 2020

Lloyd's Register
Foundation

W1119-0093 (2/2)

CSA

30 JAN 1923

Ylirindist ermy

no glo' Deol. gl.

1804

be forced on

08	"	SA-96	
09	"	SA-98-SI	
10	"	SA-98-SI	
11	"	SA-98-SI	
12	"	SA-98-SI	
13	"	SA-98-SI	
14	"	SA-98-SI	
15	"	SA-98-SI	
16	"	SA-98-SI	
17	"	SA-98-SI	
18	"	SA-98-SI	
19	"	SA-98-SI	
20	"	SA-98-SI	
21	"	SA-98-SI	
22	"	SA-98-SI	
23	"	SA-98-SI	
24	"	SA-98-SI	
25	"	SA-98-SI	
26	"	SA-98-SI	
27	"	SA-98-SI	
28	"	SA-98-SI	
29	"	SA-98-SI	
30	"	SA-98-SI	
31	"	SA-98-SI	
32	"	SA-98-SI	
33	"	SA-98-SI	
34	"	SA-98-SI	
35	"	SA-98-SI	
36	"	SA-98-SI	
37	"	SA-98-SI	
38	"	SA-98-SI	
39	"	SA-98-SI	
40	"	SA-98-SI	
41	"	SA-98-SI	
42	"	SA-98-SI	
43	"	SA-98-SI	
44	"	SA-98-SI	
45	"	SA-98-SI	
46	"	SA-98-SI	
47	"	SA-98-SI	
48	"	SA-98-SI	
49	"	SA-98-SI	
50	"	SA-98-SI	
51	"	SA-98-SI	
52	"	SA-98-SI	
53	"	SA-98-SI	
54	"	SA-98-SI	
55	"	SA-98-SI	
56	"	SA-98-SI	
57	"	SA-98-SI	
58	"	SA-98-SI	
59	"	SA-98-SI	
60	"	SA-98-SI	
61	"	SA-98-SI	
62	"	SA-98-SI	
63	"	SA-98-SI	
64	"	SA-98-SI	
65	"	SA-98-SI	
66	"	SA-98-SI	
67	"	SA-98-SI	
68	"	SA-98-SI	
69	"	SA-98-SI	
70	"	SA-98-SI	
71	"	SA-98-SI	
72	"	SA-98-SI	
73	"	SA-98-SI	
74	"	SA-98-SI	
75	"	SA-98-SI	
76	"	SA-98-SI	
77	"	SA-98-SI	
78	"	SA-98-SI	
79	"	SA-98-SI	
80	"	SA-98-SI	
81	"	SA-98-SI	
82	"	SA-98-SI	
83	"	SA-98-SI	
84	"	SA-98-SI	
85	"	SA-98-SI	
86	"	SA-98-SI	
87	"	SA-98-SI	
88	"	SA-98-SI	
89	"	SA-98-SI	
90	"	SA-98-SI	
91	"	SA-98-SI	
92	"	SA-98-SI	
93	"	SA-98-SI	
94	"	SA-98-SI	
95	"	SA-98-SI	
96	"	SA-98-SI	
97	"	SA-98-SI	
98	"	SA-98-SI	
99	"	SA-98-SI	
100	"	SA-98-SI	

350

© 2020

Lloyd's Register
Foundation

