

Less  
Less  
En  
Tax

COPY FOR LONDON OFFICE.

CABLEGRAMS: NYMDIBLE, NEW YORK.

TELEPHONES { 1363 } RECTOR  
                  { 1364 }

LLOYD'S REGISTER  
LONDON

LLOYD'S REGISTER OF SHIPPING,  
17 BATTERY PLACE,

Senta

REC'D JUN 20 1917  
ANS'D

NEW YORK      June 15, 1917.

Dear Mr. Scott;

With reference to your letter of the 17th ultimo respecting the San Francisco Report No. 2477 of survey held on the steamer "REGULUS", I enclose herewith the San Francisco Surveyors' reply to my inquiry from which it will be seen that the rivets in the treble rivetted butts of shell plating are spaced  $3\frac{1}{2}$  diameters apart in accordance with the Rules-the actual measurements being  $3\frac{1}{2}$  inches in the quadruple rivetted butts and 3-1/8" in the treble rivetted butts.

The first entry reports show these measurements to have been inadvertently reversed.

Yours faithfully,

*R. P. Hutchins*

Andrew Scott, Esq.,  
LONDON.

Encl.



© 2020

Lloyd's Register  
Foundation

W1157-0182

F-0183

W1157-254



Referred to the Chief Ship Surveyor.

as  
29/6/17

JUN 29 1917

J.M.  
30/6/17

FILED

FILED

FILED

FILED



© 2020

Lloyd's Register  
Foundation



REGISTRATION: FREE

COP

Less  
B  
Tax

B

judgment, default, or neglect