

1m.9.20.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME St. Tw. Sc. "WAIRANGI" Report Gls No. 55326

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Ist Entry When due

☒ 100A1 "with freeboard"

2 Dks & Shelter Dk, 4th Dk in No.3 hold

Cell LB 431' 2413t, FPT 122t, APT 171t

FK, Duct Keel in way of No.3 hold, 8 HH (Coll HH to Shelter Dk 7 HH to 2nd Dk), pt. Cem. Lloyd's A & CP

B 196', F 65'



© 2020

Lloyd's Register
Foundation

W1158-0171