

in this seam were removed, and it was observed that  
each rivet was fractured through the shank at the  
bottom of the countersink on the water side. All

"CHUMBLEIGH"

Lon. Rpt. No. 110593.

It is submitted a copy of the  
attached Report 10 and sketch be forwarded to the  
Marine 'A' Division, Empire Hotel, Blackpool.

T.O. CLOSED. (W.E.)

*Copies handed to Fbd. Dept.  
by M.N.T. 8/5/42*

3.9.42

W1163-2125

I am, Dear Sir,  
Yours faithfully,