

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Date of writing Report 27 Jan 1943 When handed in at Local Office 27 Jan 1943 Port of Middlesbrough  
 No. in Survey held at Middlesbrough Date, First Survey 14 Jan Last Survey 20 Jan 1943  
 Reg. Book. 71975 on the Wood, Iron or Steel S.S. CORABELLA  
 TONNAGE: Built at Sunderland By whom J. L. Thompson & Son When 1937 - 8  
 GROSS 5682 Owners Saguenay Terminals, Ltd. Owners' Address (If not already recorded in Appendix to Register Book)  
 UNDER DK. 5128 Managers (Port belonging to) London  
 NET 3373

Surveyed Afloat or in Dry Dock? Afloat Name of Dock L.N.E.R. Dk. Afloat. Destined Voyage

Cell D B or D B a feet; u E & B. feet; f feet  
 total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 8749 Port L.A.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules and Items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Voyage repairs.

Now done, vessel afloat.

No 2 hatch, one steel corner failed, and a fracture repaired by Electric welding.

A leak in the aft hold tank top repaired.

A deadlight and side light glass renewed

Some minor repairs effected.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

## PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Souppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter <u>2 1/16</u>
Frames	Have pumps been examined and found efficient?	Planking <u>to</u>	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board.)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size.
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel, so far as now seen is in good condition, and eligible in my opinion to remain as classed without fresh record of survey.

Survey Fee (per Section 29)	£ : :	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£ : :	19
Travelling Expenses (if chargeable)	£ : :	Received by me,
Second Surveyor's Fee (if any)	£ : :	19

Committee's Minute As now is  
 Character Assigned As now is

F. M. Sutcliffe  
 Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation