

12 SEP 1941

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME.....CORABELLA.....Rpt. Nfl 1957  
Hpl No 18185

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

8.41. The 1st S.S. No. 1 became due

The ST. JOHNS NFL. Surveyor reports (2.41) the vessel placed in dry dock, bottom coated, and on account of damage through heavy weather 28 rivets in sternframe renewed and a number of corroded rivets in No. 2 hold (p.s) renewed or caulked and welded.

Minor repairs effected.

The WEST HARTLEPOOL Surveyors report the vessel placed in dry dock, bottom coated, and a few rivets in sternframe welded.

It is submitted the vessel appears worthy to remain as classed with record of survey 8.41.

100A1  
8.41 Hpl



© 2020

6.11.10  
10/9/41  
Lloyd's Register  
Foundation