

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

"CORABELLA".

Rpt.

Nwc. No. 97392.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/6/92.

Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~


Machinery partly examined.

Wear and tear repairs:- Superheaters repaired;
boiler stop valves overhauled; circulating pump engine repaired.

Damage due to propeller striking a quay:-

Propeller repaired and screw shaft (cracked) renewed.

It is submitted the vessel is eligible to remain
as classed with notation S(N)4,39.



26.5.39.



© 2020

Lloyd's Register
Foundation

W1168-3201