

No. 1480.

Copy for M/c Report

4/11/35

SPARE GEAR FOR BAUER WACH TURBINES.

<u>Symbol No.</u>	<u>Part.</u>	<u>No. off.</u>
Z1T1-100	1" bolts & nuts for turbine casing joint.	4
Z1T31-100	7/8" studs & nuts for turbine bearing keeps.	2
Z1T37-1 & 2	Ford. turbine main bearing complete.	1
Z1T39-1 & 2	Aft " " " "	1
Z1T43-2	Port turbine thrust block pads.	12
Z1T44-2	Starbd " " " "	12
Z1T43-4	Liners for turbine thrust block, Port.	2
Z1T44-4	" " " " starbd.	2
Z1T15-11	Spring for turbine safety valve.	1
Z2T3-3	" " " " governor.	1
Z2T3-4	Washers " " "	1 set.
Z3T1-1	Spring for turbine governor valve.	1
Z1T51-3	Brass strip for gland labyrinths.	1/2 set.
Z1T51-4	" " " " "	1/2 "
Z35A1	Tubes for cooler (port)	10%
Z35A2	" " " (starbd)	10%
rt. ZEL39-4 )	Inspection glass for turbine ford.	1
arbd ZEL40-4 )	bearing oil drain.	1.
rt. ZEL41-4 )	Inspection glass for turbine aft	1.
arbd ZEL42-4 )	bearing oil drain.	1.
rt. Z1T1-17	Glass for water gauge on turbine.	1.
arbd. Z1T2-17	" " " " " "	1.

