

3 AUG 1939

ed by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "REINBEK". Rpt. Ham. No. 24135.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."— *Extract from Sub-Committee's Report, 24/5/92.*)

The Hamburg Surveyors report this vessel examined afloat and on account of damage/during heavy weather, temporary repairs have been effected to the seams of the centre line strake of the tank top plating of No.1 hatchway, found leaking, by replacing rivets by tap bolts.

The Surveyors recommend permanent repairs to the riveting of double bottom centre line strake in way of No.1 hatchway at the Owners' convenience.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As now, subject etc.

J. W. W.

h.f.

© 2020
2039



Lloyd's Register
Foundation

W183-0194