

ANGLO-IRANIAN OIL COMPANY
FORMERLY ANGLO-PERSIAN OIL CO.
LIMITED.
PLEASE REPLY TO
BRITISH TANKER CO. LTD.

TELEPHONE:
NATIONAL 1212.

TELEGRAMS:

INLAND: BRITTANKOL, TELEX, LONDON
FOREIGN: BRITTANKOL, LONDON.



OUR REFERENCE

ENGNG.

YOUR REFERENCE

Please address your reply to—

P.O. BOX No. 6,
NEW ZEALAND AVENUE,
WALTON-ON-THAMES,
SURREY.


Telephone Number: Walton-on-Thames 2485.
Telegraphic Address:
Inland—Brittankol Telex Sunbury-on-Thames
Foreign—British Tanker Sunbury-on-Thames

W12-0076(2/2)

LONDON, E.C.2.

27th. March, 1941.

The Secretary,
Lloyd's Register of Shipping,
"High Close",
Wiltshire Road,
WOKINGHAM, Berks:



Dear Sir,

m.v. "BRITISH STRENGTH".

We are in receipt of your letter of the 25th. inst.
relative to the notation of No. 2. Special Survey for
which we thank you.

With regard to the Screw Shaft Survey, this ship
was drydocked at Tilbury last month and it was our intention
to carry out the Survey then. The drydock was however
urgently needed for another ship also there was an acute
shortage of labour. As the wear-down of the Shaft was
only 3/32" and everything external was in order, it was
agreed between your local Surveyor and our Superintendent
Engineer to defer the drawing of the shaft to a more
favourable opportunity.

Yours faithfully,

BRITISH TANKER CO., LTD.

J. H. Kenyon
SUPERINTENDENT ENGINEER



© 2021

Lloyd's Register
Foundation

W12-0076(2/2)

ANGLO-IRANIAN OIL COMPANY
FORMERLY ANGLO-PERSIAN OIL CO.
LIMITED.
PLEASE REPLY TO
BRITISH TANKER CO. LTD.

TELEPHONE:
NATIONAL 1212.

TELEGRAMS:
INLAND: BRITANKOL, TELEX, LONDON
FOREIGN: BRITANKOL, LONDON.

OUR REFERENCE


ENGNG.
YOUR REFERENCE

BRITANNIC HOUSE.

FINSBURY CIRCUS,
LONDON, E.C.2.

27th. March, 1941.

The Secretary,
Lloyd's Register of Shipping,
"High Close",
Wiltshire Road,
WOKINGHAM, Berks:



Dear Sir,

m.v. "BRITISH STRENGTH".

We are in receipt of your letter of the 25th. inst.
relative to the notation of No. 2. Special Survey for
which we thank you.

With regard to the Screw Shaft Survey, this ship
was drydocked at Tilbury last month and it was our intention
to carry out the Survey then. The drydock was however
urgently needed for another ship also there was an acute
shortage of labour. As the wear-down of the Shaft was
only 3/32" and everything external was in order, it was
agreed between your local Surveyor and our Superintendent
Engineer to defer the drawing of the shaft to a more
favourable opportunity.

Yours faithfully,

BRITISH TANKER CO., LTD.

J. H. Kenyon
SUPERINTENDENT ENGINEER



© 2021

Lloyd's Register
Foundation
W12-8076 (1/2)

