

COPY.

of letter, dated 3.7.40.

25 JAN 1943

4m,5,42.

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "ST. SUNNIVA" REPORT Hul. No. 51855

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The HULL Surveyors report the vessel placed in dry dock, bottom coated and a considerable part of the 1st S.S. No.3, due 5.43, held.

To complete the S.S:- Examination of holds, tween decks, bunkers, machinery spaces, ceiling, plating in way of sidelights, hatches, general equipment, handpumps and ventilators.

Testing of D.B. tanks.

Verification of freeboard.


It is submitted the vessel is worthy to remain as classed with record of survey 12.42.

100A1
With freeboard
12.42 Hul.

NOTE:- The vessel has been fitted out as a "Rescue Ship" and has been chartered to the Admiralty.

Wals
20.1.43

© 2019 S.S. PART HELD.



Lloyd's Register
Foundation

No. of 3 B. 15

State if now ranged yes