

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 7/3/1921 When handed in at Local Office 7/3/1921 Port of West Hartlepool

No. in Survey held at WEST HARTLEPOOL Date, First Survey 15/2/21 Last Survey 15/2 1921
Reg. Book. (No. of Visits one)

~~Boat~~ on the ~~Wood, Iron or Steel~~ Magina Master

TONNAGE:— Built at Sunderland By whom W Gray & Co (1918) Ltd When 1920 ✓
GROSS 6800 Owners British India Steam Nav. Co Ltd Port belonging to Glasgow.

UNDER DEK. 6101 Owners' Address _____
NET 4200 (if not already recorded in Appendix to Register Book).

Surveyed ~~Afloat or in~~ Dry Dock? Yes Name of Dock Central Destined Voyage _____

WB=CeIlDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. _____ Port _____

CHARACTER, * for Special Survey, Date of last Survey and of Periodical Surveys. Years Assigned and expired. Machinery and Boiler Surveys (including date of N.B., if any).
100 A1
Shelter Deck with freeboard
(Class Contemplated)
Steam Turbs.
Society's Freeboard (if assigned) as painted on Ship and now verified } _____ft. _____ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? _____
Was a damage report made by anyone else? If so, by whom? _____

REPAIRS, OR EXAMINATION AS PER RULE, FOR First Entry.

Vessel placed in dry dock, bottom and rudder cleaned, examined and recoated and found in good order.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Paired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Feet.) When put on, Month _____ Year _____
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Boats
Waterways	State if Tanks now tested	Scuppers	Masts, Yards, &c.
Coamings	Bulkheads	Cargo Hatchways	Condition, how ascertained
Beams & Fastenings	Ceiling	Hatches	(State if wedges removed)
Outside Plating	Cement or Asphalt (state which.)	Planking of Wood Vessels	Sails
Caulking of ditto	Steering gear and its connections	Caulking	Equipment letter
Rivets	Windlass	Transoms	anchors, No. of
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Transoms	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	length _____ size _____ (on board)
Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Rule length _____ size _____
Reverse Frames		Stringers, Clamps & Shelves ditto	Hawser & Warps
Floors		Salting (State if examined.)	Standing & Running Rigging
Keelsons			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

For the information of the Committee.

Survey Fee (per Section 28)	£			Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£			✓ 19
Travelling Expenses (if chargeable)	£			Received by me,
Second Surveyor's Fee (if any)	£			✓ 19

Thomas E. Sowden.

Surveyor to Lloyd's Register of Shipping.

Committee's Minute
Character Assigned

FRI. 30 SEP. 1921

see minute on T.E. reports



W1200 - 0184

Is Certificate required? If so, to be sent to