

as per Rule 410 5 1/2 Moulded 54 0 Do. do. do. do. Second Deck Beams 27 2 1/2 17 7 Moulded depth, ft. 38 ins. 3. To Bridge Dk. Dk.

CABLEGRAMS: NYMDIELE, NEW YORK

N.N. "THEODORE"

TELEPHONES { 220 } WHITEHALL { 221 } { 222 }

6

LLOYD'S REGISTER OF SHIPPING,

17 BATTERY PLACE,

NEW YORK

December 26th, 1923.



Dear Mr. Hill:-

s.s. "ATLANTIC", N. Yk. Rpt. No. 23340.

With reference to your letter of the 10th instant, regarding this and other reports from the American Committee of the 7th ult., I am advised by Mr. J. S. Heck, the Surveyor in this case, that the height of the tank side brackets above the base line and the riveting of the butts of the sheerstrake in way of the bridge are as required, and that the steel was tested by the American Bureau, the test being in keeping with the Society's Rules.

Yours faithfully,

J. French

J. F. Hill, Esq.,

London.



© 2021

Lloyd's Register Foundation

W1232 8134

BEAMS, Bridge Deck, Angle, Ball, Angle, Plate, } Top Ball, Channel.....	7	3.44	.35	7	3.44	.35
Angles on upper edge						

DECK, Material and thickness.....	
Forecastle Deck Stringer Plate, b'dth & th'kns	
Angle on ditto	

To Mr. Drake

9.1.21

RECEIVED

NOV 11 1921

NOV 11 1921

RECEIVED

RECEIVED

NOV 11 1921

RECEIVED

RECEIVED

© 2021

Lloyd's Register Foundation



BEAMS, Bridge D

as per Rule