

REPORT of SURVEY for RE.

Date of writing Report 19... When handed in at Local Office 19... Port of

No. in
Reg. Book

Survey held at

Date, First Survey

(No. of Visits)

on the Wood, Iron or Steel

Lynghaug

TONNAGE:-

Built at

Vancouver B.C. By whom Wallace Ship

GROSS 2829

Owners

Johan Aviden Rederi A/S Owners' Address

UNDER DEK 2527

Managers

Johan Aviden

Port belonging to

NET 1693

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

feet

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification

precisely as in Reg

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 2244

Port Bgn

4100 A
6.30

2.8.1. No. 2.27

28.3/32

2.10.30

UNDERTAKING CASE

Society's Freeboard (if assigned) as
painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-

Renewed
Removed and Faird or Repaired
Faird or Repaired in place

Shell Plates. Frames. R. Frames. Floors. Beams. Str. Plates. Dk. Plates. Other Items :-

PRESENT CONDITION OF THE

| | | | |
|----------------------|---|------------------------------------|------------------------------|
| Decks | State if Tanks have been examined inside | Dblng. Plates under Sounding Pipes | Copper, or Y.M. on |
| Caulking of Decks | State if Tanks now tested | Engine Room Skylights | (State if on F |
| Coamings | Bulkheads | Coal Bunkers, Open'gs, Lids, &c. | When put on, M |
| Beams & Fastenings | Ceiling | Scuppers | Boats |
| Outside Plating | Cement or Asphalt (State which.) | Cargo Hatchways | Masts, Yards, &c. |
| Breasthooks | Rudder | Hatches | Condition, how ascerta |
| Transoms | Steering gear and its connections | Planking of Wood Vessels | (State if wedges |
| Frames | Windlass | Caulking | Sails |
| Reverse Frames | Have Pumps now been examined and found effi- | Treenails | Equipment letter |
| Longitudinals | cient? | Breasthooks & Stemson | ditto |
| Transverses | Have Sluice Valves now been examined and found | Transoms, Pointers, & Crutches | ditto |
| Floors | efficient? | Timbers of Frame at openings | ditto |
| Keelsons | Have Watertight Doors now been examined and found | Ditto Ditto at other places | ditto |
| Stringers | efficient? | Stringers, Clamps & Shelves | ditto |
| Inner Bottom Plating | Have Ventilators and their Coamings been examined | Salting | ditto |
| | and found efficient? | (State if examined.) | Standing and Running Rigging |

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent on this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,2,4," or "to remain as classed and to have record of survey, 1,2,4, and the notations of ss No. 1-24 and ptND24, &c."

| | | | | |
|--|---|---|---|-------------------|
| Survey Fee (per Section 20) | £ | : | : | Fees applied for, |
| Special Damage or Repair Fee (if any) (per Sec. 20) | £ | : | : | 19. |
| Travelling Expenses (if chargeable) | £ | : | : | Received by me. |
| Second Surveyor's Fee (if any) | £ | : | : | 19. |

Committee's Minute

TUE. 7 MAR 1933

Character Assigned

Referred

TUE. 21 MAR 1933

Surveyor to Lloyd

© 2020

Lloyd's Register
Foundation

W1245-0082