

-5 AUG 1941

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SEL'S NAME.....STONEPOOL.....Rpt.....Brs.....No.....14769

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

For conditions of class and other outstanding items see endorsement 30.12.40.

The 1st S.S. No. 3, due 7.40, has been partly held.

The BRISTOL Surveyors report the vessel placed in dry dock, bottom coated and a General Examination made with results generally satisfactory.

Owing to labour difficulties, repairs to after peak tank and shell plate at lower part of ash shoot, as above, could not be effected. The parts are efficient meanwhile, and are recommended to be specially examined at the next dry docking or General Examination.


The Surveyors recommend a notation of 'Examined 7.41', valid for 12 months, be assigned.

It is submitted action be deferred and the Surveyors' recommendation concurred in.

Insert in S.R.L Exd. 7.41 (12 mos)

Amend in S.R.L Rps to A.P. tank & shell plate at ash shoot to sp. ex. next dry docking or next G. Ex.

(DOCKING DATE 7.41)



© 2021

Lloyd's Register
Foundation

W125 - 0094