

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Sit Sc* "STONEPOOL" Rpt. Mdb No. 13365.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

*1<sup>st</sup> Long.*  
 Transverse No. 11931 Depth "d" ✓  
 Framing: Table No. - Description *channel frames as approved.*  
*2<sup>nd</sup>* Longitudinal No. 33463.  
 Proportions  $\frac{\text{Length}}{\text{Depth}} = 13.75$   
~~Deck~~ Sheerstrake *as approved.*

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✦ 160 A.1 (Steel)  
 1 A2 (SCL)  
 Hull S.B. 352' 1398T; F.P.T. 168T, A.P.T. 159T.  
 FK, 6 BH, Gen, Lloyds A+CP.  
 P 30', B 229', F 41'.

*[Signature]*

*SJR.*  
24.7.28



© 2021

Lloyd's Register Foundation

W125-0101 (1/2)

P.T.O.

is concluded that the scantlings of the  
cessite deck beams are <sup>as</sup> approved and the  
y double bottom tank under boilers has  
m tested, but the Surveyors should be  
requested to state if this is so.

Limit 27.7.28

S.G.R.  
24.7.26



© 2021

Lloyd's Register  
Foundation