

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "SAN FLORENTINO" Rpt. Nwc. No. 94673 ✓

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

The Newcastle Surveyors report this tanker placed in dry dock, bottom cleaned and coated and on account of damage due to heavy weather a shell plate found fractured renewed and one repaired, a number of rivets in shell and bulkheads renewed and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 1,37.

100AL Shell etc with Hd.
1,37 Nwc.
Carrying petroleum in bulk
Fitted for oil fuel etc.

W.S.



© 2019
15.2.37
Lloyd's Register
Foundation
W128-0104