

W1281-0182

2m.10.33.

1

30 JUN 1935

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME "IJORA" Report Lon No. 101533a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey _____

When due _____


The Boiler Survey became due 5,35.

In reply to the usual Notice the Owners write that the boilers of this vessel are now under the inspection of the U.S.S.R. and they therefore do not require any further surveys to be carried out by this Society.

It is submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu of withdrawal of class at the Owners' request.

Withdraw class
Insert ...

The Certificate of Classification to be endorsed "*Cargo battens not fitted*" and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register
Foundation