

T.S.S. "ESSEQUIBO".

The electric light installation on this vessel has been fitted in accordance with the Rules with the exception that the main cable from the dynamo to the main switchboard is somewhat smaller in diameter than would be required by the present Rules if the total amperage of which the dynamo is capable were passed through it.

The Belfast Surveyors point out that there are many motors in this vessel and the generating plant is in excess of the full requirements of the vessel, and it is therefore unlikely that the full power can ever be used, and they recommend that this cable should be accepted in this instance. It has been arranged that in the sister vessel the full requirements of the Rules will be complied with.

It might be noted that the cable in question is larger in diameter than would have been required by the Society's previous Rules.

It is submitted that in the circumstances the electric light installation should be approved in this instance.

Lt. 30/11/14

J.M.

A.R.R.

27.11.14.



© 2021

Lloyd's Register
Foundation