

Chief Ship Surveyor .....

Received from Chief Ship Surveyor 30 MAY 1933

SHIP NAME Steel S.S. "HELLE" Rpt. Os1 No. 4050

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." —Extract from Sub-Committee's Report, 24/5/92).

Survey .....

*See made*

The Oslo Surveyors report this vessel placed on floating dock, minor repairs effected and the bottom coated.

Some rivets in coal bunkers have been temporarily repaired by electric welding and the Surveyors recommend these rivets and a number of wasted shell rivets in coal bunker be renewed at the next dry docking.

The engine seating has been renewed, a new engine having been fitted.

It is submitted the vessel appears worthy to remain as classed with record of survey 4,33 subject as recommended.

100A1 ) subject etc.  
4,33 Os1 )

*CLC*  
*26/5/33*

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be entered in the Register Book.



© 2021

Lloyd's Register Foundation