

2m.12.32.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

126 APR 1938

VESSEL'S NAME "RAPIDO".

Report Lon.

No. 103334a.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 23/5/32))

Nature of Survey _____

When due _____

The Boiler Survey became due in 1,37.

In reply to enquiry the Naples Surveyor forwards a letter received from the Owner, who states that he intends to keep the Registro Italiano Class of this vessel only.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu thereof indicating withdrawal of class at Owner's request.

Withdraw class
Insert ...



©2021

Lloyd's Register
Foundation

W13/20145