

damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

3m,7,35.

POSTPONED SURVEYS.

Tw. Sc.

Case of the Steel/Train Ferry "CHANGKIANG".

No. 56780 in Reg. Bk. 2862/1347 tons, Built 1933-2

Classed +100 A1 7.33 Owners Ministry of Railways of the Republic of China.
Train Ferry + Line 2.33 Port of Registry OG.
for river service

Survey Due Screwshaft Survey due 2,36.



© 2021

Lloyd's Register
Foundation

W1315-0324

of funnel(s)
ted under steam
ed under steam?
y. Boilers?
y Boiler?
y Boiler?
fitted at the af
eing efficiently l
the after end
ciently lubricate
r bearing of scre
power fitted?