

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report..... 19... When handed in at Local Office..... 19... Port of London

DISCLOSED  
BOX No. 163.

No. in Survey held at Prabhavati Date, First Survey 1933 Last Survey 9

Reg. Book. 3208 Steel Twin Se. (No. of Visits)

TONNAGE: Built at Glasgow By whom Harland + Wolff, La. When 1933 MONTH 9

GROSS 556 Owners Bombay Steam Nav. Co. Owners' Address Bombay

UNDER DK. 474 Managers Bombay Port belonging to Bombay

NET 205

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=Cold Bor.DBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted  
total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4759<sup>a</sup> Port Bom.

CHARACTER. & for Special Survey. Date of last survey and of Periodical Surveys. Year Assigned or expired. Machinery and Boiler surveys (including date of N.B., if any).  
+ A1. 11.33 + sub 9.33  
With freeboard  
For Boating Service  
Bombay + Goa  
Fitted for Oil Fuel 9.33  
F.P. ABOVE 100° F.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	E. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed .....								
Removed and Faired or Repaired .....								
Faired or Repaired in place .....								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year
State if Tanks now tested	State if Tanks now tested	Dblng. Plates under Sounding Pipes	When put on, Month Year
Bulkheads	Bulkheads	Engine Room Skylights	Boats
Ceiling	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Cement or Asphalt (State which.)	Cement or Asphalt (State which.)	Oil Bunkers	Condition, how ascertained (State if wedges removed)
Rudder	Rudder	Scuppers	Sails
Steering gear and its connections	Steering gear and its connections	Cargo Hatchways	Equipment letter
Windlass	Windlass	Hatches	Anchors, No. of
Have pumps now been examined and found efficient?	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Chain Locker
Have Sluice Valves now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Cables (State if now ranged)
Have Watertight Doors now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Treenails ditto	length (on board) mean diam.
Have Ventilators and their Coamings been examined and found efficient?	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Rule length size
		Transoms Pointers, & Crutches ditto	Hawser & Warps
		Timbers of Frame at openings ditto	Standing and Running Rigging
		Ditto Ditto at other places ditto	
		Stringers, Clamps & Shelves ditto	
		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 29) .....	£	Fees applied for, .....	£
Special Damage or Repair Fee (if any) (per Sec. 29) .....	£	Received by me, .....	£
Travelling Expenses (if chargeable) .....	£		
Second Surveyor's Fee (if any) .....	£		

Committee's Minute FRI 9 JUL 1937  
Character Assigned withdraw class  
Surveyor to Lloyd's Register of Shipping.  
General Committee Thursday 15 July 1937  
Decision of Classing Committee confirmed W/317-0116

Is Certificate required? If so, to be sent to