

2m, 10, 38.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

ELSA ESSBERGER

Report Pld.

No. 1546

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

STERN FRAME.

When due

Subject to rudder post of stern frame (EW 5,39) being specially examined at next dry docking.

& to vessel being dry docked for further examination & permanent repairs upon arrival at home port.

(B)

C.E.F.

W. H. H.



10.7.39

© 2021

Lloyd's Register Foundation

insert new condition in SRL.

W1352-0110