

Kindly note that the Lower  
Front End Plate marked "S"  
has been altered from  $1\frac{1}{32}$ " to  
 $1\frac{1}{8}$ " thick to suit Owners Specification

Lloyd's Register  
Foundation

W. Hadlet

W148-0146.1