

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... When landed in at Local Office... Port of New York

No. in Survey held at... Res. Book... Date, First Survey... Last Survey... 19

50099 on the Wood, Iron or Steel S. S. "ACCOMAC" Master...
TONNAGE:-
GROSS 5274 Built at San Pedro Cal By whom Los Angeles S.B. & M.C. When 1918 6
UNDER DEK 50/2 Owners U. S. Shipping Board (Emergency Fleet Corp.) Port belonging to Los Angeles
NET 45321 Owners' Address... not already recorded in Appendix to Register Book.

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
WB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER...
+100A1-8-19
Fitted for full
6-81-1904
+LMC 6-18
BS-3-70
WTC
Society's Freeboard (if assigned) as painted on Ship and now verified

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?
Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR
RETAIN
See copy of letter attached, dated 23rd December, 1920, received from the United States Shipping Board, requesting the withdrawal of class.

DISCLOSED SECTION
No. 63

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faird or Repaired ...								
Faird or Repaired in place ...								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.) When put on, Month Year
Decks	Inner Bottom Plating	Engine Room Skylights	Boats
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Waterways	State if Tanks now tested	Scuppers	Condition, how ascertained (State if wedges removed)
Coamings	Bulkheads	Cargo Hatchways	Sails
Beams & Fastenings	Ceiling	Hatches	Equipment letter
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	Anchors, No. of
Caulking of ditto	Rudder	Caulking ditto	Cables (State if now ranged)
Stretches	Steering gear and its connections	Treenails ditto	length size (on board)
Stretches & Crutches	Windlass	Breasthooks & Stemon ditto	Rule length size
Stretches	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Stretches	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	Standing & Running Rigging
Stretches	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	
Stretches		Stringers, Clamps & Shelves ditto	
Stretches		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Survey Fee (per Section 28)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute New York JAN - 4 1921

Character Assigned Withdraw class

Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday, 20 January 1921
Lloyd's Register
American Committee
Foundation
decision confirmed

W1505-0078

10m. 8.19. - Transfer 1
The Surveys are requested not to write on or be

To Certificate required if so, to be sent to