

LLOYD'S REGISTER, REGISTER OF SHIPPING,
LONDON. 17 BATTERY PLACE

RECD NOV 4 1918

NEW YORK October 18, 1918.

AMSD
OK. 14/11

Dear Mr. Scott:

With reference to your letter of the 10th ultimo and to San Francisco report No. 2778 on the steamer "ACCOMAC", I enclose herewith a letter dated the 12th instant received from the Surveyors from which it will be seen that the screw shaft of this vessel is not fitted with a continuous liner, the liner being in three pieces and burned at the joints as required by the Rules.

This information also applied to the following cases:-

"Wakulla"
Wassaic

"Wampum"
West Galoc

With kindest regards,

Yours faithfully,

A. P. Mitchell

A. Scott, Esq.,
LONDON.



© 2021

Lloyd's Register
Foundation

W 1505-0079

For Mr Mayne

78 No

NOV -4 1918

Three lines Toulabe
considered as
continuous being
the 3 legs the are
brought together

A. R. L.
7/14/18



© 2021

Lloyd's Register
Foundation