

Surveyors: 2-9-18

Received from Chief Surveyors

NAME

Shelss Accorinae

Report

S-Lo

No. 2778

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

Survey

When due

The Anchors have been tested by the Surveyors to the American Bureau & the Chain cables at Tipton & the New York Committee have assigned the notation of axes.

Intermediate bulkheads in fore & after holds have been dispensed as approved. Letter from Owners received.

* 100 A-1 (Steel)

2 576 (Steel)

Cell 573 356' 1104 L. F.P.T. 108 L. A.P.T. 241 L

F.K. Intermediate Bulkheads in fore holds & after holds dispensed with: 5 BH only "pt. Cen. axes.

Page B 115

©2021



Lloyd's Register
Foundation

W 1505-0081