


✓ 6 pads, with pins, for H.P. turbine adjusting block.

Y.P.S. Cambria "

Gls. 41541.

It is concluded that one set of valves and one bucket and rod for the lubricating oil pump are included in the articles of spare gear, but this should be confirmed.



© 2021

Lloyd's Register  
Foundation

W1506-0208

Thickness of shell plates ✓

Material ✓

Description of longitudinal joint ✓

Diameter of rivet holes