

NET
Surveyed

CB=Cell

al cap

S.B.-A

the

tanks e

and e

H

i s

Rej

ot

ry of the
sent p

Box 1515

Box 1515

A.P. JONES

therepresentative of the American shipping board, surveyor and
"LAWSON" of Philadelphia for slight collision damage
stated to have been ~~caused~~ caused by being struck by the
"VINE D'ORAN" of Marseilles.
For further particulars see Log Books.

POOP.

On starboard side of poop, some rails and awning stan-
chions had been buckled and now faired.
One awning pole broken to be replaced.
On starboard side of bridge, one bridge sheer stroke plate at
upper edge above gunwale angle bar slightly set in, this does
not effect the efficiency of the vessel and can be faired if
considered necessary.

A.P. Jones

Surveyor to
Lloyd's Register of Shipping
Marseilles.

Fee as per account :

£ 85.00



© 2021

Lloyd's Register
Foundation

W1515-0134

Box

1515