

W1521-0132

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME Steel S.S. "MAXTON" Rpt. Hul. No. 32009

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey _____

To complete the Survey:
Decks to be retreated.

New pins to be supplied to several of the Engine Room skylight-hinges
3" Bower Anchor to be replaced by one of correct weight & test.
Equipment of wires & ropes to be supplied.

Freight to verify.

The Newcastle Surveyors should be advised & requested to forward a report on
on 8 when the survey has been completed.

The Hull Surveyors should be requested to state the spacing of Bridge deck beams.

The Newcastle
pcd/much to Hull

in letter
7/8/92

© 2021

Lloyd's Register
Foundation

W1521-0133